POTE AL HAZARDOL IDENTIFICATION AND PRELIM		ALGION SITE NUMBER (IN be ac-
NOTE: This form is completed for each potential hazardous we submitted on this form is based on available records and may be and on-site inspections.	iste site to help set priorities for e updated on subsequent forms as	site inspection. The information a result of additional inquiries.
GENERAL INSTRUCTIONS: Complete Sections I and III through usessment). Fife this form in the Regional Hazardous Waste Agency; Site Tracking System; Hazardous Waste Enforcement	Log File and submit a copy to: U	.S. Environmental Protection
	ENTIFICATION	
Riders Disposal Area	East Bank. of Him D. STATE E. ZIP CODE	ekston Run
East Taylor Tup G. OWHER/OPERATOR (II known)	PA 15907	Cambria
1. NAME	15,907	2. TELEPHONE NUMBER
Bethlehem Steel Corp., 119 Walnut	St., Johnstown PA	814-533-7774
1. FEDERAL 2. STATE 3. COURTY 4. MUN	ICIPAL S. PRIVATE 6.	UNKNOWN
I. SITE DESCRIPTION Steep stream valley used by Bethlehem Steel Corp. (Also the lands	ed as an industrial owner) for more than	waste disposal site
J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.)		K. DATE IDENTIFIED
Company notified state, state in	spections date back	to + Nov. 18,969
L. PRINCIPAL STATE CONTACT	Marte Specialist	2. TELEPHONE NUMBER
1. NAME William R. Shawley - Solid	waste operation	814-472-5081
II. PRELIMINARY ASSESSME	NT (complete this section last)	
1. HIGH X2. MEDIUM 3. LOW 4. NORE	s. unknown	
B. RECOMMENCATION	all and another distributed control or supplies the subsection of the supplies of the supplies of the supplies and the supplies of the supplie	
1. NO ACTION NEEDED (no hezard)	2. IMMEDIATE SITE INSPEC	
2. SITE INSPECTION NEEDED TENTATIVELY SCHEDULED FOR:	b. WILL BE PERFORMED	BY:
b. WILL BE PERFORMED DY:		ED (low priority)
William Shawley		
C. PREPARER INFORMATION 1. NAME	2. TELCPHONE NUMBER	13. DATE (mo., day, & yt.)
William R. Showley - Solid Waste Spec	814-475-508	1 11-30-83
III. SITE II	REORMATION	
A. SITE STATUS 1. ACTIVE (Those industrial or municipal airos which are being used for weste treatment, attenge, or disposal or usualizating basis, even if Info-	(Those sites that include such inc. no regular or continuing use of the	idonia ilko "midnighi dumping" where sitako Exerci di troppi, has occurred.)
Present active area about 13 after about 235 acres.		Direction of Operations
B. IS GENERATOR ON SITE!		JAN 3 1983
1. NO 2. YES (apoclly gene	rnter's four-digit SIC Gode): (5)	ID WACTE
C. AREA OF SITE (In acres) D. IF APPARENT SERIOUSH	ESS OF SITE IS HIGH, SPECIFY CO	ORDINATES MANAGEMENT
Approximately 250 acres 400 21' 30	C E A C C	54 -10"
Approximately 250 acres 400 21' 36 E. ARE THERE BUILDINGS ON THE SITES	Nation.	

III) OTHER (speally,

							subtract the	OF	RIGINAL	
ELATE	או ס	ORMA	TION	(continued	7) -,	***************************************		73	(Red)	1
MAY D	F ON TH	OF SIT	F fulac	a in descar	ulina ordine	of harnest				ı

3. LIST SUBSTANCES OF GREATEST CONCERN WHICH Fe Mn sludges containing 0.2% CN

Dusts and sludges containing Fe, Pb, Cd, disposed of in landfill without impermeable base. Also Goal Tan sludge,

3). waste acids dumped in highly permeable slag fill area.

a. ADDITION DECOMMENTS OF NARRATIVE DESCRIPTION OF SITUATION KNOWN OR REPORTED TO EXIST AT THE SITE.

DER and Bethlehem Steel Comp. are currently working on a consent order to address the waste piles, and the mill scale

	8.	(eing accumulated.
A. TYPE OF HAZARD	POTEN- TIAL HAZARD (mark 'X')	ALLEGED INCIDENT (mark 'X')	D. DATE OF INCIDENT (mo.,day,yr.)	E. REMARKS
1. NO HAZARD				
2. HUMAN HEALTH	X			
3. NON WORKER 3. INJURY/EXPOSURE				
4. WORKER INJURY				
6. CONTAMINATION OF WATER SUPPLY				
6. CONTAMINATION OF FOOD CHAIN				
7. CONTAMINATION OF GROUND WATER	Х			
6. CONTAMINATION OF SURFACE WATER	X			
DAMAGE TO FLORA/FAUNA	•			
10. FISH KILL				
11. CONTAMINATION				
2. NOTICEABLE ODORS				
13. CONTAMINATION OF SOIL	-	·		
14. PROPERTY DAMAGE			•	
IA. FIRE OR EXPLOSION		•		
16. SPILLS/LEAKING CONTAINERS/ RUNOFF/STANDING LIQUIDS	·			
17. DRAIN PROBLEMS				
16. EROSION PROBLEMS				
10. INADEQUATE SECURITY	-			-
20. INCOMPATIBLE WASTES				
21. MIDNIGHT DUMPING				
2. OTHER (specify):				. \
22. OTHER (specify):				\

VII. PERMIT INFORMATION OPIGINAL							
A. INDICATE ALL APPLICABLE PERMITS ASLD BY THE SITE. (Red)							
1. NPDES PERMIT 2. SPCC PLAN 3. STATE PERMIT (specify):							
A. AIR PERMITS 5. LOG	. AL AIR PERMITS						
Part B Submitted.	TA TREATER						
10. OTHER (specify): Applica	ation for per	rmit for sc	ecure land fill at Riders,				
B. IN COMPLIANCET Waste Pile storage longer than one year, 1. YES 2. NO 3. UNKNOWN Not on impermeable base, not protected from precipitation or wind.							
4. WITH RESPECT TO [11st regul							
		AST REGULATO	RYACTIONS				
Consent Order of 6-23	es (summorize below,	tinued dispos	al of waste pickle liquor at Riders Jan. 83				
Ferromanganese pit	closed by a	consent de ci	ee 4-6-79.				
	IX. INSPEC	TION ACTIVITY	(past or on-going)				
☐ A. NONE 🔀 B. YE	S (complete Items 1,2	7,3, & 4 below)					
1. TYPE OF ACTIVITY	2 DATE OF PAST ACTION (mo., doy, & yr.)	3. PERFORMED BY: (EPA/State)	4. DESCRIPTION				
RCRA Inspection	10-26-83	state	Haz, waste inspection of waste pile Records Check. Sampled groundwater wells				
Groundwater Monibering	8-22-83	EPA & State					
RCRH Inspection	7-20-83	state	Haz. waste inspection of Riders. Also checked records.				
	X. REM	EDIAL ACTIVITY	(pust or on-going)				
A. NONE D. YE	S (complete Items 1,	2, 3, & 4 bolow)					
I.TYPE OF ACTIVITY	2. DATE OF PAST ACTION (mo., day, & yr.)	3.PERFORMED BY: (EPA/State)	4. DESCRIPTION				
Consent order & Agreement	Now Pending	StateDER	Closure of slag-acid neutralization area Closure of waste Pile and Mill Scale food				
Consent order a Agreement	6-22-82	State DER	Discontinuation of warte pickle liquor disposal at Riders.				
Sonsent Decree = Agreement	9-6-79	DER SEPA	Discontinuation of waste pickle liquor disposal at Riders. Closure flan for Ferro manganese pit at Riders.				
NOTE: Based on the information in Sections III through X, fill out the Preliminary Assessment (Section II) information on the first page of this form.							

FIELD TRIP SUMMARY REPORT

	ould be prepared in T2070-2), so that a	proper site ra	ating can be as	signed.
me of Site	Rider's Dispo	sal Area	PA-78	4
Section 30	active, has owner/op O of RCRA. Yes X) Note EPA I.D. No	NO PAD 0043	44222	
If the answ observation a sketch ma) Is the site a gene hazardous waste? ers submitted in Par s warrant a more tho p showing those area e, monitoring wells,	t VI (Hazard De brough site inve s of concern.	landfill also escription) of lestigation/samp	at Riders. (See Part 8) EPA Form T2070-2 or ling, please attach
Mary B	Waste Specialist			•
_Mary B DER Solid	Waste Specialist	- William S		· · · · · · · · · · · · · · · · · · ·
Mary B DER Solid Site observ	loom, Lab Superv	- William S opo map).	kawley 81	· · · · · · · · · · · · · · · · · · ·
Mary B DER Solid Site observ A. Populat 1. 0-1	Waste Specialist ations: (attach a t	- William S opo map). of the site is	kawley 81	•
Mary B DER Solid Site observ A. Populat 1. 0-1 2. 10-3 3. gre B. List su	Waste Specialist ations: (attach a t ion within 1000 ft. 0 people 100 people	opo map). of the site is (woodlot, agri	(CHECK ONE)	4-473-5081
Site observed. A. Populate 1. 0-1 2. 10-3. gree B. List sur Horth: South:	Waste Specialist ations: (attach a t ion within 1000 ft. O people 100 people ater than 100 people rrounding land use:	- William S opo map). of the site is (woodlot, agri	Kawley 81 (CHECK ONE) icultrual, play	4-473-5081

С.	Wat	er s	upply for area. (CHECK ONE)
	1. 2. 3	Mun	face intakes (locate on attached map) icipal wells (locate on attached map) estic wells:
	•		Approximate number within & mile. 2 Locate a minimum of 3 wells on attached map and list below: Unknown at Present Time
			Property owner Unknown at Tresent
		•	Address
· · .			Phone No.
			Well records YES NO YES NO YES NO Odor problems YES NO YES NO YES NO Taste problems YES NO YES NO YES NO
		c.	If odor or taste problems are reported please elaborate:
D.	YES	X Were	face or subsurface, (leachate), drainage areas from site apparent? NO . If yes: leachate seeps were noted in 1975. No recent investigation since Fe Hn pit cleved and acrd dumping cere unusual odors or stains noted? YES X NO stressed vegetation noted? YES X NO If yes please note area on map.
Ē.	If y	yes, sity,	eams or receiving waters adjacent to site? YES X NO list observations: (i.echange in benthic community, change in plant diversity, change in color, siltation, etc.).
	Str	eam	studies done in 76 from sampling done in 73 and 75 indicated
			pollution problems in Hinckston Run which were attributed to site.
	No	stn	fam study done since Felln pit was closed or since acid dumping was stopp
F.			pography: (i.eplateau, strip mine ravines, etc.). Steep stream
			with up to 150 feet of fill consisting of coal waste and plant refuse.
G.		•	oservations: (i.eerosion, located in flood plain, etc.).
			of plant waste and coal waste has created a wide relatively
			ench on the slope with a very steep side slope down to
			for Run,

FIELD TRIP SUMMARY REPORT

٧.	Were photographs taken? YES NO X If \$\infty\$s: Who has custody of photos?	
	Name:	
• •	Agency:	
	Phone No.:	
VI.	Is a hydrogeological survey for this site If no, Section III D of EPA Form T2070-2	attached? YES NO X must be completed.
VII.	Please attach pertinent copies of reports (i.eState monitoring data, consultant r	or data reviewed by inspector: eports, etc.).
/111.	Name of Inspector: William R	, Shawley - Solid Waite Specialist
	Agency: Pennsylvania Dept of Env.	Rebures, Bur of Sold Works Mgmil
	Phone No.: 814 - 475 - 508	
	Time on Site: ~ 8 hours during last	3 inspections
	Weather Conditions: Surry and dry	

Beth Stel PA28 ORIGINAL (Red)

I. Waste Related Information

It should be to the (continued)

C. 2. Amounts of waste

DOCK - 14,500 TONG

Also at Riders are the following wastes:

- 1.) Mine refuse dumped prior to 1960 when Rosedate. Hine was closed. Probably several million tons.
- 2.) Brick, dirt, and plant cleanup waste (Nonhazandous)
 At least 1,000,000 Tons since 1967
 Probably several million Tons Total.
- 3.) Coal Tar Decanter Sludge Probably 6,000 Tons since 1976
- 4) Open Hearth Electrostatic Precipitator Dust Approx. 72,000 Tons since 1476
- 5) Basic iron filter cake and dust Approx. 84,000 Tens stockpiled as of 1976
- 6) Hoz. Waste file since 1985 all manifested wastes Totals

 KO61 11,000 TOLS

 KO62 16,000 TOLS

 KO87 515 TOLS

 DOC6 3850 TOLS

SUBJECT: Report of Field Investigation Riders Disposal Area Bethlehem Steel Corporation East Taylor Township, Cambria County PA-784

TO:

Wilbur I. Taxis Regional Solid Waste Director Williamsport Regional Office

FROM:

William S. Hanczar Regional Soil Scientist Williamsport Regional Office

Dale P. Voykin Regional Geologist Williamsport Regional Office

Robert O. Young Geologist Lewistown Office

This report is written as an attempt to formalize some of the data obtained during several field investigations at the Bethlehem Steel Riders Disposal Area.

Riders Disposal Area, utilized by Bethlehem Steel Corporation (Johnstown) for the disposal of solid and liquid waste, is located along the east bank of Hinckston Run north-northeast of Johnstown. This site, approximately 2 miles in length, can be found on the Johnstown 7-1/2' quadrangle (7-8.3)—see Map #1.

The disposal site is situated on a steep hillside forming the east embankment of Hinckston Run. Over the years, filling at the Rider disposal site has developed three (3) distinct levels (level #1 at the bottom, level #2 midway, level #3 at the top).

Structurally, the site is located on the east limb, near the axis, of the Johnstown Syncline. Bedrock, gently dipping (N22E, 2W), consists of the Pennsylvanian Conemaugh Formation (cyclic sequences of red and gray shales and siltstones with thin limestones and coals).

Groundwater, on the east bank of Hinckston Run, moves in a westerly direction towards Hinckston Run because of topographic and structural controls.

Measurements at springs and a few dug wells upslope of the disposal area and just downslope of Headrick Union Cemetery indicate that perched conditions exist with water at or near the natural ground surface year-round. Because Hinckston Run is a regional discharge zone and because of permeability contrasts between the refuse and natural ground, all flow in the vicinity of the pile (perched or otherwise) must ultimately discharge to Hinckston Run. Since discontinuities in the perched zone at the contact at the base of the pile can exist, the only difference between perched flows from the pile and those flows entering the regional system is travel time and, perhaps, some dilution.

Soils at the site consist primarily of Ernest silt loam, typically deep and moderately well-drained, containing a fragipan or moderately slowly permeable layer at 18 to 36 inches and Summerhill-Gilpin very stony silt loam, typically deep and well-drained. The Ernest soils have developed in silty materials which have washed and/or slid from the uplands. The Summerhill-Gilpin soils have developed either in colluvium which has washed and/or slid from the uplands or in residuum from weathering shales, siltstones and fine-grained sandstones. Essentially, the entire site has been covered by the waste slag and/or coal refuse. Other soil types associated with the Gilpin Complex may well be present, exhibiting varying depths to bedrock and varying drainage conditions.

According to information received from Bethlehem Steel, there are five basic types of waste disposed of at the Rider site. They are as follows:

- 1. Coal Refuse
- 2. Blast Furnace, Ferromanganese Slag
- 3. Gas Cleaning Sludge (Ferromanganese Blast Furnace Filter Cake)
- 4. Waste Pickling Acid (pickling liquor)
- Miscellaneous Material (liquid and solid)

Since the miscellaneous solid materials are largely composed of dirt and brick (with minor amounts of wood, paper, etc.), our major concern has been items 1 through 4. The disposal areas for these items are shown on Map #1.

For a typical analysis of these materials (with the exception of coal refuse), we excerpt the following material (submitted by Bethlehem Steel Corporation to Timothy J. Bratton on February 9 and 23, 1972):

RIDERS AREA: January 1, 1971 - November 30, 1971

2.	Bla	st Furnace, Ferromanganese Slag	Tons
	-	one produced during August, September	
	a.	Amount produced	72,500
	b.	Amount manganese metal recovered	1,570
	c.	Amount recycled to furnace	245
	d.	Amount to landfill	70,685
	e.	Ferromanganese slag analysis - Typical	

Component	<u>z</u>
Si0 ₂ Al ₂ 0 ₃ Ca0 Mg0	24.3 17.0 36.3 12.4

% Dry Basis

Mn0		5.50
S		2.12
Ti02		0.45
Fe0		0.47

- 3. <u>Gas Cleaning Sludge</u> Ferromanganese Blast Furnace Filter Cake
 - a. Amount to landfill disposal (wet) (None produced during August, September and October because of furnace rebuild.)
 - b. Filter Cake Analysis Typical % Dry Basis

Component	<u>%</u>
S10 ₂	11.0
Ca0~	12.3
Mg0	6.30
A1203	8.92
Fe203	1.89
К20	3.40
Na ₂ 0	0.85
ZnÕ	1.35
Mn0	23.63
Ignition Loss	25.03
so ₄	4.64
~7	

Tons

74,700

4. Chemical Wastes - Waste Pickling Acid

Waste acid includes the following types of acid used and quantities disposed of by neutralization on slag:

Waste Acid	Quantity, Tons	7 of Total 90.5 9.5	
Sulfuric Hydrochloric	79,500 4,218		
Total	83,718	100.0	

5.

a.	Mis	Tons	
	1)	Scrap wood	1,100
•	2)	Paper, shavings, rags, etc.	3,540
	3)	Dirt from plant clean-up, brick	•
		pieces, etc.	58,400
	4)	Total	63,040

Item "a" materials are covered by ferromanganese blast furnace filter cake.

b. Miscellaneous Plant Liquid Wastes - 2500 tons

This material is defined as slurry from the ferromanganese blast gas wash water recycle system. Occasionally filter cake production lags the amount of dust produced by the furnace and these solids accumulate in the thickeners. When this occurs, the excess thickener underflow is pumped into tank trucks and hauled to the disposal area where the slurry is drained onto slag. Mechanical repairs to the thickeners may be necessary. While such repairs are infrequent, the thickener must be drained. Since drainage to the stream cannot be permitted, the water is pumped into tank trucks for disposal on slag. Analysis of the water is attached. See Table #1.

We note in all past correspondence to the Department, that there has never been any written data as to the amount of coal refuse (if any) that is disposed of at this site. Further, the area designated for coal refuse on Map #1 has also been used for slag disposal.

From our observation, we offer the following description of methods of waste disposal:

- 1. Coal Refuse We have not seen coal refuse being deposited at the site; however, in that area designated for coal refuse (see Map #1) the refuse stands at the angle of repose, is highly eroded, and lacks any apparent coeff or vegetation.
- 2. Slag This material is (presently) hauled to level #3 by rail and the cupolas are dumped over the side. No attempt at compaction or cover is made.
- 3. Filter Cake This material is hauled in a liquid state by tank trucks to the northern end of level #3. It is poured into a large ravine which has been dammed(by slag) to prevent the material from flowing overland to Hinckston Run. This material ponds behind the slag dam, eventually dewaters, and dries to a rubber-like consistency. One can note the formation of interesting desiccation features, meander patterns, and natural levees in the resulting "mudflat".
- 4. Pickle Liquor This material is hauled to the area designated for its disposal on level #3 by tank trucks. The pickle liquor disposal pits consist of shallow trenches, approximately 2-4 feet deep x a bulldozer blade wide x 30-40 feet long, excavated into the waste slag and lined with a thin layer of crushed limestone. The tank trucks back into the pits, open the valve at the back of the tanker, and discharge their contents. Generally, several pits are in use and, periodically, at some schedule we are unable to determine, they are abandoned, covered, and new pits are constructed. The disposal operation, therefore, shifts from the southcentral portion of level #3.
- 5. <u>Miscellaneous Materials</u> <u>Miscellaneous liquid waste</u> is dumped in the filter cake area and miscellaneous solid waste (paper, etc.) is presumably incorporated with the waste slag dumping operation.

In an effort to determine what effect the Rider Disposal Area has on Hinckston Run, the writers have sampled this stream on various occasions since November 1973. On one such occasion, November 8, 1973, Hinckston Run was sampled jointly by the Department and representatives of Bethlehem Steel Corporation. The sampling point locations, shown on Map #2, are described on Table #2.

All samples requiring a heavy metals analysis were first fixed with concentrated HNO₃ in the field to lower the pH < 2 and all samples requiring cyanide analysis were first fixed with concentrated NaOH to raise the pH > 12, prior to shipment to the Department laboratory. Field pH measurements were accomplished with the use of both a Hach Color Comparator and a Leeds & Northrup electric pH meter (Model # 7417). Field specific conductivity readings were accomplished with the use of an Aquatronics

Conductivity Analyzer (Model 320). The results of these samplings are shown on graphs #1 through #16b and Tables #2 through #6.

Results, recorded in parts per million (ppm) or in parts per billion (ppb), were recorded on 5-cycle semi-logarithmic paper. Semi-log paper was chosen because of the wide range in values found which would be difficult to show on normal graph paper. It should be emphasized that each log cycle represents a 10-fold increase over the preceding cycle. Further, trace or lower limits were sometimes graphed differently for results obtained from the Department lab and those obtained from Bethlehem Steel's. For example, when our lab reported a lower limit of less than 50 ppb, the result was graphed at the base of the log-cycle (10 ppb); whereas, because of the manner in which Bethlehem Steel reported their lower limits, a result of less than 50 ppb was graphed one unit lower (40 ppb). This manner of graphing tended to smooth out the Bethlehem Steel curves.

Because of numerous constraints (lack of personnel, time, number of stations, number of samples per station, etc.), after the initial sampling (11/8/73), only those parameters we felt were absolutely necessary were sampled. In that process, some new parameters were added (e.g., As) in later sampling and some were deleted (e.g., Fe, Mn, Cl, nitrates, BOD, COD, phenols, etc.) Hindsight, superior to foresight, we now realize that most parameters should have been carried through from beginning to end-regardless of the burden on field or lab personnel. Further, it should be stressed that although some key parameters were sampled and requested, interference often prohibited analysis by the laboratory (e.g., cyanide and chlorides in waste pickle liquor).

Because of flow conditions (e.g., BS13, Table #6) and/or lack of time, all stations were not sampled during each succeeding sampling period. For these reasons, some portions of some graphs are only extrapolations and are indicated as such with (?).

The normal sampling points are numbered 22 through 1. Point 22 at the Hinckston Run Reservoir and Point 1 is at the first road bridge above the Conemaugh River, within the plant proper. There are also several waste samples, background samples and special stream and seep samples given numbers beyond 22. All sampling point locations and descriptions are listed on Table #2 and shown on Map #2.

Graphing of the sampling results (see graphs 1-16b) reveals distinct changes downstream of the Hinckston Run Reservoir. It becomes apparent that there is a minimum of three distinct patterns in the stream graphs—that area from BS33 to BS17, BS16 to BS2, and BS2 to BS1.

stream.

Generally, in the area from BS33 to BS17, sampling results reveal uniform conditions and relatively good water quality. West bank tributary samples (outlined in blue) tend to mirror the results of stream quality in this reach. For these reasons, we consider this area (BS33-BS17) and the west back tribs to constitute background conditions. Further, at present, no disposal operations are carried out in this area—although, in the past, it was the site of slag disposal. In fact, leaching from these old slag

areas could account for small peaks in some parameters in this stretch of

That stretch of stream between BS16 and BS2 indicates obvious elevated levels for all parameters and indicates highly degraded water quality conditions in Hinckston Run. This stretch of stream is also the area where all waste from Bethlehem Steel, earmarked for the Riders Disposal Area, is placed along the east bank.

From observation of the general locations of waste disposal on Map #2, one would expect that the immediate effect of leaching from the filter cake disposal area would be in the vicinity of samples BS16 to BS14, and that from the pickle liquor in the vicinity of BS12-BS7. However, from actual observation of traceable waste flows (e.g., BS31), we know that considerable overlap in both directions (up and downstream) occurs. For example, on 7/24/75 we first observed a waterfall (ES31) entering Hinckston Run from the east bank (flow at 1330 hrs approximately 100 gpm). This flow was traced uphill to level #2, then 1,500 feet southward along the railroad tracks to the swamp on level #2--directly below the area of pickle liquor disposal on level #3 (at that time). Four hours later (1730 hrs), the flow at BS31 had decreased to a trickle. Results for samples taken on that day indicate fairly uniform concentrations of all parameters for samples BS31 (waterfall), BS34 (pickle liquor) and BS36 (swamp level #2), indicating that pickle liquor was short circuiting through level #3 to the swamp and then running overland across level #2 to discharge into Hinckston Run (BS32). At its point of entry (ES32), the stream changed from white to a blood red color. More importantly, this acid discharge was approximately 1,500 feet upstream (BS32) of the area expected (BS12) for an acid seep. Further, although such blatant discharges are not seen on every occasion, acid seeps (BS13) are noted beginning in the vicinity of the waterfall (whether dry or flowing) on every sampling occasion.

Obviously, with changing pickle liquor disposal pit locations, one can expect changes in acid seep concentrations along the east bank of Hinckston Run. For example, if the northern pickle disposal pits are used, one can expect higher concentrations in the upstream seeps (BS13 to BS37); whereas, when the southern disposal pits are used, one can expect higher concentrations downstream (BS12 to BS6). This point can best be demonstrated by observation of seeps BS6 and BS9. On 11/8/73 and 11/18/75 these seeps were

distinctly alkaline (pH 10-12). On 5/10/76, BS6 had a field pH of 3.2 (see graph #1) with an approximate point flow of 10 gpm. We believe that, with extended use of a disposal pit, piping occurs. When pit locations are changed, ground water passing through the alkaline slag and moving in pipes that formerly resulted in an acid seep could, presumably, result in an alkaline seep—hence, the high pHs at BS6 and BS9.

Piping occurs from the reaction of the acid pickle liquor reacting with the alkaline slag. As neutralization occurs, each subsequent load of acid extends the pipe development. Also, as neutralization occurs, some elements found in the pickle liquor are precipitated; whereas, other elements within the slag may go into solution. This process can explain variances in the chemistry of the seeps from BS13 to BS6.

The elevated parameters on the graphs, with respect to the disposal operations at the Rider site, appear to be substantiated by visual observation of the stream conditions from BS16 to BS2. Beginning at BS19, white seeps are noted along the east bank. By BS16, the stream has changed from clear in nature to a chalky white color, bank to bank. On some occasions (e.g., 7/24/75), the stream becomes beet red in the vicinity of station 13 (acute change). On other occasions (e.g., 5/10/76), during low flow periods, the stream takes on a slight green tinge in the vicinity of BS13 and becomes gradually darker downstream.

Beyond BS2, one notes (see graphs) a distinct drop in all parameters between stations BS2 and BS1. We attribute this decrease to dilution. Estimates of stream flow on 11/8/73 (floating ball, yardstick, and stopwatch) show an approximate four-fold increase in flow (1,150 gpm to 4,100 gpm) between BS2 and BS1. We feel that this increase is mainly due to cooling water discharges at the Bethlehem Steel plant. We must point out, however, that the concentration of most parameters, though lower than those at BS2, is well above that which would be allowed in a permitted discharge to the Conemaugh River (e.g., 5,160 ppb cyanide on 7/24/75).



SUMMARY AND CONCLUSIONS:

To date, Bethlehem Steel has maintained that, to the best of their knowledge, the method of pickling liquor disposal at the Riders Disposal Area, as well as their solid waste disposal, has not appreciably lowered the quality of Hinckston Run. Further, they have implied that the obvious degradation below the reservoir is due to acid mine drainage.

We feel that, based on physical observation, chemical data, and analysis of the parameters associated with a known mine discharge (BS3), this is not a problem due to acid mine drainage and the degraded conditions in Hinckston Run can be directly attributed to the waste disposal operations (solid and liquid) by Bethlehem Steel Corporation at the Riders Disposal Area.

Bethlehem Steel also maintains that their method of liquor disposal is a viable method, because of neutralization with the alkaline slag, of industrial waste disposal. Observation of any of the graphs reveals that this is not the case. Further, although some neutralization does occur at present, with continued use of this method of liquor disposal we are of the opinion that the slag dump will become so riddled by pipe development that the resultant effect will be even greater degradation of Hinckston Run.

Graphing of the sample parameters, generally, substantiates our opinion as to the source(s) of the pollutants in Hinckston Run. Some irregularities do appear but they can be due to:

- 1. sampling technique
- 2. instrumentation errors
- 3. laboratory errors
- 4. seasonal variations in ground water flow conditions and temperature
- 5. variations in waste characteristics and areas of disposal

We cannot explain the chemistry of some of the irregularities in the highly toxic elements (e.g., As, Cn, Pb) but their mere presence can be attributed to the waste disposal operations. Those parameters considered less toxic (e.g., Fe, Mn, SO4, etc.) and easily sampled and analyzed show no irregularities and point directly to the waste disposal operations as their source.

To conclude, Bethlehem Steel Corporation waste disposal operations at the Riders Disposal Area are responsible for the polluted (in the strictest sense of the word) nature of Hinckston Run below the reservoir.

WSH:DPV:ROY:mm


cc: Division of Industrial Waste (BWOM) Division of Solid Waste Management Ground Water Section Soils Section

Mr. Arnold, BWOM Lab

Mr. Bossert Mr. Gummo /Mr. Neal


ORIGINAL (Red) JOHNSTOWN QUADRANC PENNSYLVANIA PENNSYLVANIA MENTAL RESOURCES 7.5 MINUTE SERIES (TOPOGR) **COLOGIC SURVEY** Hinckston Rua Re. Goods T. A. Y Pleasant Hill Stutzman CONEMAUGH eleter of own

ORIGINAL



Mapz

KEY					
7.5 Minute Topographic Map					
5	Strike and dip of bedrock strata				
	Approximate area of deep mining				
	Access road				
	Bethlehem property line				
	Approximate area for secure landfill				
O	Water well				
Δ	Spring				
⊠	Test boring				
5	Test pit				
	Groundwater flow direction				
,					



RIDERS DISPOSAL AREA RECORDED INVENTORY OF WASTE MATERIALS

A. Current Waste Materials - Nov. 12, 1976

1. Ferromanganese Blast Furnace

Gas Wash Water - Filter Cake Sludge

Production Rate:

10,000 T/Month

Analysis				% Dry Basis	
Ignition	Loss			25.0	
MnO				22.8	
. SO ₄	•			5.8	
SiO ₂				10.4	
CaO ~				11.9	
Al ₂ O ₃				8.9	
Fe ₂ O ₃				2.0	
ZnO		•		1.2	
MgO				6.3	
K20				3.2	
Na ₂ O				0.7	
CN				0.2	
% Moistur	e			70% <u>+</u> 5	ક

2. Ferromanganese Blast Furnace Slag

Production Rate:

9,500 T/Month

Analysis	% Dry Basis
SiO ₂	24.3
Al ₂ O ₃	17.0
CaŌ	36.3
MgO	12.4
MnO	5.5
S	2.1
TiO ₂	0.45
B/A	2.0
FeO	0.5

Waste Acid

Production Rate:

14,150 T/Month (includes flushing water)

Analysis	<u>*</u>
Free Acid (CaCO ₃) Total Iron (Fe)	3.3 3.2

RIDERS DISPOSAL AREA RECORDED INVENTORY OF WASTE MATERIALS

(continued)

4. Solid Waste (brick, dirt, sinter waste, etc.)

Production:

5,900 T/Month

5. Material stockpiled for recycling (Inventory to 8/31/76)

a. FeMn flue dust
b. Basic iron filter
cake and dust
c. Basic iron dust
d. Baghouse dust
4,800 Tons
81,000 Tons
2,600 Tons
700 Tons

6. Combustible Waste (paper)

Flash Incineration by hot slag: 540 T/Month